Part Number Update

Bulletin No: PNU-096-000-A Effective Date: 5/01/04 Cancels: NA Page: 1 of 1

subject: ABS Gen 4/5 Service Replacement Numbers

Below is a listing of Bendix part numbers and the corresponding Gen 4/5 ABS service replacement numbers. Replacements for obsolete part numbers are listed where applicable.

Bendix	Aftermarket
Part	Replacement
Number	rtopiacomoni
300069	None
300125	801802
300126	801802
300130	801764
300143	801763
300144	801753
300149	801755
300199	801765
300208	801759
300209	801802
300222	801752
300223	801802
300239	801802
300325	801763
300342	801752
300343	801760
300344	801753
300345	801755
300365	801766
300366	801767
300367	801756
300368	801757
300398	801761
300410	801763
5006806	801753
5006807	801802
II30224	None
II39776F	None
5012608	801762
5012582	801754
5012926	801758